


FIG. 1



09989407.112101

FIG. 2





FIG. 3



09989407 112101

FIG. 4

40

40a

40b

40d

40e

40f

40g

40c

! SET PRIORITY END INSPECTION

XXXX/XX/XX

...SECTION

FRONTAL THORAX

OVERVIEW OF PELVIS

OVERVIEW OF SKULL

...

...

NEW IMAGE

R

RETAKE IMAGE

ADD

DELETE

▲ ▼

DETAIL

FILM

NUMBER OF DIVISION

SIZE

AP/PA

QA


AUTO

SHELTER

ID# 123456... FUJI ...


40/

FIG. 6




09989407 112104

FIG. 7



0958447 112004

FIG. 8



09989407 11 101